

# RFP #24-024 School Bus Seat Replacement and Repair

## Tabulation

<b>A. PLEASE CERTIFY THE FOLLOWING STANDARDS ARE MET.</b>	Yes	No	Exceptions
1. FMVSS 302 flammability			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
2. Boston Fire Block Test			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
3. FMVSS 222 impact protection			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
4. ASTM 3574 foam physical properties			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
5. Replacement foam is <u>ONLY</u> high-impact rebond material.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
6. Replacement foam is manufactured by Triad-Fabco.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair		✓	Heavy Duty Bus Parts
7. Replacement foam has knee-impact styrofoam wedges.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
8. Replacement foam must have canvas insert to prevent frame breakthrough.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
9. FMVSS 302 fire retardant vinyl must be installed on 1993 and older bus models.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
10. 1994 to current bus models must have Prevail/Proform Fire Block Vinyl installed.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
11. All seat covers must be custom made with a uniformed tail for stapling.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
12. All seat covers installed must be stapled with 20 staples minimum.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
13. True Liquid Vinyl is to be used in repairs			
<b>NO GLUE; NO CEMENT</b>			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		
14. Fire Block mesh is to be used on all repairs.			
National Guaranteed Vinyl, Inc.	✓		
Maloy Vinyl Repair	✓		

<b>B. PRICES FOR THE FOLLOWING SERVICES:</b>		Each	Maximum Percentage Increase (not to exceed)	
			Year 2	Year 3
1.	Seat foam replaced			
	National Guaranteed Vinyl, Inc.	\$19.50	0%	0%
	Maloy Vinyl Repair	\$23.50	2%	2%
2.	Back foam replaced			
	Thomas			
1	Maloy Vinyl Repair	\$24.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
	Bluebird			
1	Maloy Vinyl Repair	\$24.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
	Wayne			
1	Maloy Vinyl Repair	\$24.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
	Ward			
1	Maloy Vinyl Repair	\$24.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
3.	Foam repair (each)			
	National Guaranteed Vinyl, Inc.	\$12.50	0%	0%
*	Maloy Vinyl Repair	N/A	N/A	N/A
4.	Vinyl patch repair			
	National Guaranteed Vinyl, Inc. Back	\$7.00	0%	0%
	National Guaranteed Vinyl, Inc. Seat Bottom	\$5.00	0%	0%
	Maloy Vinyl Repair	\$8.00	0%	0%
5.	Vinyl back cover replaced (standard flame retardant)			
	National Guaranteed Vinyl, Inc.	\$14.75	0%	0%
	Maloy Vinyl Repair	\$18.50	2%	2%
6.	Vinyl seat cover replaced (standard flame retardant)			
	National Guaranteed Vinyl, Inc.	\$11.75	0%	0%
	Maloy Vinyl Repair	\$12.50	2%	2%
7.	Vinyl back cover replaced (fire block vinyl)			
	Maloy Vinyl Repair	\$23.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
8.	Vinyl seat cover replaced (fire block vinyl)			
	National Guaranteed Vinyl, Inc.	\$17.50	0%	0%
	Maloy Vinyl Repair	\$18.50	2%	2%
9.	Driver seat foam replaced			
	National Guaranteed Vinyl, Inc.	\$14.50	0%	0%
	Maloy Vinyl Repair	\$24.50	2%	2%
10.	Driver back foam replaced			
	National Guaranteed Vinyl, Inc.	\$14.50	0%	0%
	Maloy Vinyl Repair	\$24.50	2%	2%

1 Not overall low average

\* No repairs made on top/side edges. Small repairs to front/back of foam pad at no charge.

		Each	Maximum Percentage Increase (not to exceed)	
			Year 2	Year 3
11.	Driver seat cover replaced (flame retardant)			
	National Guaranteed Vinyl, Inc.	\$18.50	0%	0%
	Maloy Vinyl Repair	\$26.50	2%	2%
12.	Driver back cover replaced (flame retardant)			
	National Guaranteed Vinyl, Inc.	\$18.50	0%	0%
	Maloy Vinyl Repair	\$26.50	2%	2%
13.	Front kick panel foam replaced			
1	Maloy Vinyl Repair	\$24.50	2%	2%
	National Guaranteed Vinyl, Inc.	\$29.50	0%	0%
14.	Front kick panel cover replaced			
	National Guaranteed Vinyl, Inc.	\$14.75	0%	0%
	Maloy Vinyl Repair	\$23.50	2%	2%
15.	Bottom brackets replaced			
	National Guaranteed Vinyl, Inc.	\$6.00	0%	0%
	Maloy Vinyl Repair	\$3.00	2%	2%

1 Not overall low average