

TABULATION
CSP #27-028 - School Bus Seat Repair

| B. PRICES FOR THE FOLLOWING SERVICES: | | Price | Maximum Percentage Increase (not to exceed) | |
|--|---------------------------------|--------------|--|---------------|
| | | | Year 2 | Year 3 |
| 1. Seat foam replaced | | | | |
| | Maloy Vinyl Repair | \$16.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$19.50 | 0% | 0% |
| 2. Back foam replaced: Thomas | | | | |
| | Maloy Vinyl Repair | \$19.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$29.50 | 0% | 0% |
| 3. Foam repair (each) | | | | |
| | Maloy Vinyl Repair | free* | 0% | 0% |
| | National Guaranteed Vinyl, Inc. | \$12.50 | 0% | 0% |
| 4. Vinyl patch repair: seat back | | | | |
| | Maloy Vinyl Repair | \$7.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$7.00 | 0% | 0% |
| 5. Vinyl patch repair: seat bottom | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$5.00 | 0% | 0% |
| | Maloy Vinyl Repair | \$7.00 | 2% | 2% |
| 6. Vinyl back cover replaced (standard flame retardant) | | | | |
| | Maloy Vinyl Repair | \$12.50 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$14.75 | 0% | 0% |
| 7. Vinyl seat cover replaced (standard flame retardant) | | | | |
| | Maloy Vinyl Repair | \$10.50 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$11.75 | 0% | 0% |
| 8. Vinyl back cover replaced (fire block vinyl) | | | | |
| | Maloy Vinyl Repair | \$18.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$29.50 | 0% | 0% |
| 9. Vinyl seat cover replaced (fire block vinyl) | | | | |
| | Maloy Vinyl Repair | \$14.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$17.50 | 0% | 0% |
| 10. Driver seat foam replaced | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$14.50 | 0% | 0% |
| | Maloy Vinyl Repair | \$21.00 | 2% | 2% |

1 Not overall low average

* Small repairs to front/back of foam pad at no charge.

TABULATION
CSP #27-028 - School Bus Seat Repair

| | | Price | Maximum Percentage Increase (not to exceed) | |
|---|---|-----------|---|--------|
| | | | Year 2 | Year 3 |
| 11. Driver back foam replaced | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$14.50 | 0% | 0% |
| | Maloy Vinyl Repair | \$21.00 | 2% | 2% |
| 12. Driver seat cover replaced (flame retardant) | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$18.50 | 0% | 0% |
| | Maloy Vinyl Repair | \$19.00 | 2% | 2% |
| 13. Driver back cover replaced (flame retardant) | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$18.50 | 0% | 0% |
| | Maloy Vinyl Repair | \$19.00 | 2% | 2% |
| 14. Front kick panel foam replaced | | | | |
| | Maloy Vinyl Repair | \$21.00 | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$29.50 | 0% | 0% |
| 15. Front kick panel cover replaced | | | | |
| 1 | National Guaranteed Vinyl, Inc. | \$14.75 | 0% | 0% |
| | Maloy Vinyl Repair | \$21.00 | 2% | 2% |
| 16. Bottom brackets replaced | | | | |
| | Maloy Vinyl Repair | \$2.00 ea | 2% | 2% |
| | National Guaranteed Vinyl, Inc. | \$3.00 ea | 0% | 0% |
| In the event of an emergency, maximum emergency response time would be | | | | |
| | Maloy Vinyl Repair | | 4 hours | |
| | National Guaranteed Vinyl, Inc. | | 24 hours | |
| | | | | |
| 1 | Not overall low average | | | |
| | | | | |
| | Overall average charge: (excluding # 3 & #16) | | | |
| | Maloy Vinyl Repair | \$14.49 | | |
| | National Guaranteed Vinyl | \$19.75 | | |